

VARISCITE LTD

EOL # 19003_AR

VAR-SOM-MX6 (REV1) VAR-SOM-AM33 (REV1) VAR-SOM-OM44

Published: Feb 15th, 2019

© 2019 Variscite Ltd.

All Rights Reserved. No part of this document may be photocopied, reproduced, stored in a retrieval system, or transmitted, in any form or by any means whether, electronic, Mechanical, or otherwise without the prior written permission of Variscite Ltd. No warranty of accuracy is given concerning the contents of the information contained in this publication. To the extent permitted by law no liability (including liability to any person by reason of negligence) will be accepted by Variscite Ltd., its subsidiaries or employees for any direct or indirect loss or damage caused by omissions from or inaccuracies in this document.

Variscite Ltd. reserves the right to change details in this publication without notice. Product and company names herein may be the trademarks of their respective owners.

Variscite Ltd. 4 Hamelacha st. Lod 7152008, Israel Phone +972 (9) 9562910 • Fax +972 (9) 9589477

Table of Contents

1.	EOL INTRODUCTION	.3
1.1	Purpose of document	3
1.2	Identifying your SOM's version	3
2.	EOL DETAILS	.4
2.1	EOL classification	.4
2.2	Products affected	.4
2.3	Actions required by customer	4
3.	LAST TIME BUY	.5
4.	LEGAL NOTICE	.6
5.	CONTACT INFORMATION	.7

1. EOL introduction

1.1 Purpose of document

The purpose of this document is to provide a single repository for explaining the End Of Life (EOL) to a specific product family. The changes described in this document are related to all product families detailed in section 1.2.

1.2 Identifying your SOM's version

SOM family	Specific configuration feature
VAR-SOM-MX6 revision 1.xx	With Wi-Fi (WB or W)
VAR-SOM-AM33 revision 1.xx	With Wi-Fi (WB or W)
VAR-SOM-OM44	With Wi-Fi (WB)

Note: revision 1.xx means revision 1 of the SOM while xx can be any specific character.

2. EOL details

2.1 EOL classification

Due to EOL of the TiWi-BLE Wi-Fi module from Laird (LSR) and the lack of FFF pin compatible Wi-Fi module, Variscite is forced to announce EOL of all products using this specific Wi-Fi module.

For customers using VAR-SOM-AM33 Rev1.xx or VAR-SOM-MX6 Rev1.xx with Wi-Fi inside, Variscite offers a <u>pin compatible</u> SoM replacement VAR-SOM-AM33 Rev2.xx or VAR-SOM-MX6 Rev2.xx using a newer Wi-Fi module from TI's WL183XMOD family.

2.2 Products affected

All product families listed in section 1.2 that use Wi-Fi inside their configuration. See below the affected part numbers:

Variscite Description	Arrow part number
VSM-MX6***W***REV1.***	V6***W***
VSM-AM33***W***REV1.***	V335***W***
VSM-OM44***W***REV1.***	N/A

Notes:

1. VSM can be VAR-SOM.

REV1.*** can be R1.***.

2. *** represents different character length and value according to the specific ordered configuration.

2.3 Actions required by customer

- Order the relevant products according to the below mentioned LTB.
- For customers using VAR-SOM-AM33 Rev1.xx or VAR-SOM-MX6 Rev1.xx with Wi-Fi inside, Variscite offers a <u>pin compatible</u> SoM replacement VAR-SOM-AM33_V2 (Rev2.xx) or VAR-SOM-MX6_V2 (Rev2.xx) using a newer Wi-Fi module from TI's WL183XMOD family. In such case, software needs to be updated to support the newer revision. Please contact <u>sales@variscite.com</u> for further details.

3. Last Time Buy

LTB period will end by June 15th, 2019, deliveries no later than December 15th, 2019.